# SAP POXY EP- 702(SF)

## Solvent Free Coal-tar Epoxy

### **DESCRIPTION:**

- SAP POXY EP- 702(SF) IS Solvent Free Coal-tar Epoxy coating based on coal-tar
  & Amine hardener
- Excellent resistance to acid & alkaline chemicals also for petroleum solvent, sulphid gases & chloride.
- High mechanical strength & abrasion resistance .
- Can be used as mortar for repairing asphalt & concrete after mixed with filler
- Excellent adhesion to many surface metal, cement, asphalt, concrete .....etc.
- Resistant for industrial sewage.
- The product can withstand temperatures continuously up to  $50\,^{\circ}\!\text{C}$  , intermittent up to  $80\,^{\circ}\!\text{C}$ .

### FIELED OF APPLICATION:

- Water proofing for underground construction such as foundation sewage pipes & brigades.
- Anti corrosive coating for concrete & asphalt surface due to excellent abrasion resistant.
- Solvent Free highly resistance to sea water.
- Water proofing for sewage plants, pipes & tanks.
- Dam proof & resist water pressure.

### **TECHNICAL DATA:**

Solid content	:	98 ±1%
color	:	Black
Pot life		90 min. at 23°C
Tack free	:	3 hour
Completely dry	:	4 days

### **INSTRUCTION FOR USE:**

- All surface must be clean, dry & free from oil, grease & rust. The surface must be completely dry, especially concrete surface.
- 2 components must be good mixed before applied.
- Apply with brush, ruler or spray.
- Second coat must be apply after one day of first coat .
- To making mortar mixing ratio 1: 4 with dry sand

### **STORAGE LIFE:**

One year (in closed containers)

### **PACKING:**

GROUP 4 kg- 20 kg

#### **HEALTH AND SAFETY**

- This is a hazardous material if misused read and understand the Material Safety Data Sheet (MSDS) before use.
- Observe the precautionary notices on the label of the container. A material safety data sheet is available upon request & national or local safety regulations should be followed. This product is intended for use by professional applicators.

- As a general rule, avoid skin-and eye contact by wearing overalls, gloves. Goggles mask, etc. Spillage on the skin should immediately be removed by through washing with lukewarm water & soap or a suitable industrial cleaner. Eyes should be flushed with fresh water & medical attention sought immediately.
- Spraying should be carried out under well-ventilated conditions. Avoid inhalation of solvent vapors & paint mist by wearing an air mask.
- This product contains flammable material & should be kept away from spark & open flames.
- Smoking in the area should not be permitted.

# ساب بوکسی (EP-702(SF)

دهان أيبوكسي معدل بالقار خالى من المذيبات .

### <u>الوصف :</u>

• ساب بوكسى (EP-702(SF) عبارة عن دهان أقتصادى عالى للكيماويات من القار المعدل بالأيبوكسى .

### المميزات:

- مقاوم للصرف الصناعي.
- منتج معتمد من هيئة مياه الشرب والصرف الصحى لعزل أعمال الصرف الصحى.
  - دهان مقاوم عالى للبرى والاحتكاك والتآكل .
  - دهان له قوة التصاق عالية بالأسطح المعدنية والاسفلتية والأسمنتية والخرسانية.
- يستخدم كمونة أيبوكسية في أعمال الترميمات الاسفلتية والاسمنتية بعد خلطه بالمواد المالئة من الرمل المدرج.

### مجالات الاستخدام:

- يستعمل كعازل أساس في عزل المواسير الخرسانية وبيارات الصرف ووحدات الصرف الصناعي .
- دهان الأساسات الخرسانية والمعدنية المدفونة في باطن الأرض للمنشآت والكبارى وأعمال الصرف الصحي
  - يستعمل لدهان المنشآت البترولية المعرضة لمياه البحر
  - دهان خارجي للخزانات والمنشآت المعدنية لحمايتها من الصدأ .
- دهان الأرضيات الخرسانية المعرضة للحركة الدائمة نظرا للمقاومة العالية للبرى وللأحتكاك والأحماض والقلويات .
- دهان خالى من المذيبات يستخدم لدهان المنشآت المعدنية والخرسانية الأفقية والرأسية مانع للتآكل ومقاوم لمياه البحر
  - ◄ يستعمل كمونة ترميم وملئ العرانيس ببيارات الصرف الصحى بعد خلطه بمادة الكوارتزالنظيفة .
    - يتحمل درجة الحرارة حتى 80° درجة مئوية .

### المواصفات الفنية:

■ المواد الصلبة : 98 ±1 %

اللون : أسود ، بنى محروق
 فترة التشغيل : 1.30 ساعة عند 23 °م

■ معدل الاستهلاك : 3-4 م/ كجم للوجه الواحد

الجفاف السطحى : 3 ساعات
 الجفاف النهائي : أربعة أيام

# طريقة الاستخدام:

- یجب أن یكون السطح المراد دهانه جاف تماما .
- يجب أن يكون السطح نظيفا خاليا من الزيوت والشحومات والصدأ .
- يجب خلط المركبين خلطا جيدا قبل الدهان ويتم الدهان بالفرشاة أو الرولة أو بالرش.

### 07/02/2

- في حالة دهان وجه ثان يتم الدهان بعد مرور يوم كامل من دهان للوجه الأول.
  - في حالة عمل مونة أيبوكسة يخلط بنسبة 1: 4 من مادة الكوارتز النظيفة

التخرين : عام في العبوات المغلقة .

العبوات : 4 كجم ، 20 كجم للمجموعة .

# لمزيد من المعلومات برجاء الاتصال بخدمة الدعم الفنى

For more information please consult our technical department.