ساب بوکسی <u>EP- 706</u>

معجون إبيوكسي لاصق وغير قابل للانكماش

<u>الوصف :</u>

■ عبارة عن معجون ايبوكسي على هيئة مركبين متوسطى اللزوجة ذو نظام خاص متوافق ذو قوام متماسك .

المميزات ومجال الاستعمال:

- ساب بوكسى EP- 706 معجون إيبوكسى ناعم له قوى التصاق كبيرة وقوة تحمل عالية للأحمال الميكانيكية ، ومقاومة عالية للأحماض والقلويات ولهذا فإنه يناسب تماما الاستخدامات الآتية :
 - ترميمات واصلاح سوك وزوايا السلالم والكمرات والأعمدة .
 - معجنة الأسطح الخرسانية والأسمنتية لتسويتها قبل أعمال الدهانات الإيبوكسية بعد تخفيفه.
 - ملء الشروخ والشقوق وأماكن التعشيش للأعمال الخرسانية
- لحام جميع أنواع المواد على البارد مثل: الحديد والخرسانة وأشاير حديد التسليح في الخرسانة ولاصق للأجزاء المعدنية والخشبية والرخام.

المواصفات الفنية :

■ المواد الصلبة : 100 %

الكثافة : 1.80 كجم / لتر

اللون : رمادي – أبيض

فترة التشغيل : 45 دقيقة في درجة 20 م

الجفاف : 8 − 10 ساعة عند 25 م

■ قوة اللحام للخرسانة : أكبر من 250 كجم / سم2

■ فترة التخزين : سنة واحدة في العبوات المغلقة .

إعداد الأسطح:

الأسطح الأسمنتية والخرسانية:

- 1. يلزم توافر سطح صلب خالي من الأجزاء المفككة والشوائب مثل: الأتربة وأملاح التزهير ومركبات معالجة الخرسانة والزيوت والشحوم.
 - 2. يجب أن تكون الأسطح جافة وألا تزيد نسبة الرطوبة عن 3 % وتكون درجة حرارة الأسطح من 10-40 سيليزيه

الأسطح المعدنية:

- 1. يلزم توافر أسطح نظيفة جافة خالية من الأتربة والشحوم والزيوت والصدأ وزوائد اللحام وأي شوائب أخرى .
 - 2. في حالة الأسطح المجلفنةأو الألومنيوم أو النحاس يلزم إجراء عملية تتميش بالأحماض المخففة .

طريقة التشغيل:

- 1. يتم خلط المركبين خلطا جيدا ، ويفضل استخدام شنيور ميكانيكي مركب عليه ساق تقليب مناسبة وبسرعة بطيئة .
- 2. للحصول على قوام مناسب لمعجنة الحوائط وتتعيمها يتم إضافة 10 20 % من ساب بوكسي إي . بي 701 للمخلوط .
 - 3. يتم تشغيل المونة الناتجة باستعمال البروة ، وسكينة المعجون / والمسطرين الصلب وذلك في فترة التشغيل المحدودة .
 - العبوات: مجموعة من مركبين زنة 1 كجم ، أو 5 كجم _ يتم الخلط بالوزن طبقا لما هو مدون على العبوات .

SAP POXY EP-706

Non- Shrink Epoxy Adhesive Putty

DESCRIPTION:

 SAP POXY EP - 706adhesive putty is solvent free two component product on the basis of modified epoxy resin with an appropriate hardening system.

ADVANTAGES AND FIELD USE:

- **SAP POXY EP 706** smooth adhesive putty has a high adhesive properties, mechanical strength, chemical resistance, so that it is highly recommendable for.
- Repair edges and corners of staircases, beams, columns.
- Smoothing cement based plasters and concrete walls before application epoxy paints.
- Filling and repairing cracks, voids, honeycombing in concrete.
- Adhesive for steel to concrete and concrete to concrete, and for the anchorage of bolts and an excellent adhesive for a wide variety of materials like marble, wood, steel.

THCHNICAL DATA:

| Solid content | : | 100 % |
|-------------------------------|---|-------------------------|
| Density | : | 1.8 Kg / L. |
| Color | : | White, grey |
| Mixing ratio | : | 1 A : 1 B |
| Processing time | : | 45 minutes at 20 °C |
| Drying time | : | 8 – 10 hours at 25 °C |
| Adhesive strength on concrete | : | 25 kg / cm ² |

DIRECTIONS FOR USE:

- The concrete or cement surface must be dry (dampness not more than 3 %), firm, free of dust, oil grease and all other impurities which can affect the adhesion.
- Steel surface must be dry, clean free from rust, oil grease.
- In case of galvanized, brass aluminum, the surfaces must be etching by diluted acids
- The two components of SAP POXY EP-706should be thoroughly mixed together using a slow speed mixer (maximum 300 r.p.m).
- To obtain suitable consistency for smoothing of walls add 10 20 % SAP POXY EP 701 to the putty.
- Apply the putty by trowel, scraper during processing time.

STORAGE LIFE:

One year (in closed containers)

PACKAGES:

- 1 & 6 Kg (group of two components).
- Follow the mixing ratios by weight indicate on the pails.

HEALTH AND SAFETY:

 Observe the precautionary notices on the label of the container. A material safety data sheet is available upon request & national or local safety regulations should be followed. This product is intended for use by professional applicators.

- As a general rule, avoid skin-and eye contact by wearing overalls, gloves. Goggles mask, etc. Spillage on the skin should immediately be removed by through washing with lukewarm water & soap or a suitable industrial cleaner. Eyes should be flushed with fresh water & medical attention sought immediately.
- Spraying should be carried out under well-ventilated conditions. Avoid inhalation of solvent vapors & paint mist by wearing an air mask.
- This product contains flammable material & should be kept away from spark & open flames.
- Smoking in the area should not be permitted.

For more information please consult our technical department.